



Actual Rebar
point
according to
the plans

Coordinates that were
given from the plans

4.8 ft

Both of these points have to be the same. Why is the difference that much and how can you reduce this discrepancy?

I'm using RTK (NTRIP over bluetooth).